Weighing Q1-W Operation Manual

100112

Power Source

100~240V 50/60hz AC INTPUT12V/1A DC OUTPUT 12W6V/4AH Lead-acid rechargeable battery included

Power Consumption

Approx. 12mA Approx. 36mA with backlight Approx. 48mA with backlight and RS232 interface

Battery hours per charge

Approx. 320 hours (backlight off)

OPTION

RS232 Interface

LOADCELL connection (for indicator)

PIN1 : E +	PIN2 : E-	PIN3 : S+	PIN4 : S -
PIN5 : SEN +	PIN6 : SEN-	PIN7 : GND	

How to display version number?

Turn on the scale and press and hold the PRINT key until the countdown sequence has completed. The LCD display will show 100112. The shown number is the main-board version of the scale. Release the PRINT key and the scale will start the functions setup

Functions description

OFF key:

Press and hold the OFF key and the display will show "oFF" for 2 seconds then the scale will turn off automatically.

ON key:

Press the ON key to turn on the scale. The scale will start self-adjusting sequence then will stabilize in 0.

UNITS / ESC key:

UNITS: To select desired weighing unit.

ESC : To escape (exit) setting in setup mode.

ZERO / ◄ key:

ZERO : To reset the weight to 0, but the displayed weight value has to be less than \pm

2% of maximum capacity.

• : To move one space to the left or downward in setup mode.

To the left

 $00000\underline{0} \rightarrow 0000\underline{0}0 \rightarrow 000\underline{0}00 \rightarrow 00\underline{0}000 \rightarrow 0\underline{0}0000 \rightarrow \underline{0}00000$

Downward

 $LF 9 \rightarrow LF 8 \rightarrow LF 7 \rightarrow \dots \rightarrow LF 1$ $UF-9 \rightarrow UF-8 \rightarrow UF-7 \rightarrow \dots \rightarrow UF-1$ $ECF-3 \rightarrow ECF-2 \rightarrow ECF-1$ $TARE / \rightarrow key:$

TARE : To subtract the container weight. Maximum tare = full capacity

• : To move one space to the right or upward in setup mode.

To the right

 $\underline{0}00000 \rightarrow 0\underline{0}0000 \rightarrow 00\underline{0}000 \rightarrow 000\underline{0}00 \rightarrow 0000\underline{0}0 \rightarrow 00000\underline{0}$

Upward

 $LF 1 \rightarrow LF 2 \rightarrow LF 3 \rightarrow \dots \rightarrow LF 9$ $UF-1 \rightarrow UF-2 \rightarrow UF-3 \rightarrow \dots \rightarrow UF-9$ $ECF-1 \rightarrow ECF-2 \rightarrow ECF-3$ $\boxed{Net/Gross / \land}$ key:

Net/Gross : To see gross and net weight when the scale is on tare status. All other keys

will be disabled when gross weight is activated.

▲ : To increase values upward in setup mode.

例如: 232 0 → 232 1 → 232 2 → 232 3 → → 232 6 **PRINT /** \checkmark key:

PRINT : Manually transmitting data through RS232 to computer or printer at normal weighing mode (RS232 setup must be set at keyboard transmission 232 3 or 232 6)

✓ : Works as enter key in setup mode

[∗] Error messages:


Err H Initial zero too high (over FULL SCALE + 10%),

		For approval models
Err	L	Initial zero too low (under FULL SCALE – 10%),
		For approval models
Err	Ν	Unstable internal count
-OL-		Overload, when the weight is heavier than the full capacity + 9d of the
scale		

Functions Setup

Approval Calibrations and Functions Setup (Lock section) L F 1 ~ 8

Standard Functions Setup $UF - 1 \sim 9$ Standard Calibrations $ECF - 1 \sim 3$



ECF-1 Weight Cal	libration :	
ECF-1	Press the <i>+</i> key to start Weight Calibration (Press the ESC	
	key to exit back to weighing mode)	
له ↓		
CALZ	Press the 4 key to calibrate zero point (Press the ESC key	
	to terminate calibration back to menu ECF-1)	
له ↓		
<u>1</u> 50.00kg	Use \blacktriangleleft , \blacktriangleright , \land , $0\sim 9$ and then \checkmark key to enter the weight to be	
	calibrated	
لې ↓	(Press the ESC key to terminate calibration back to menu	
	ECF-1)	
150.00kg	Place the required weight mass onto the scale as indicated on	
	display and press the \prec key to calibrate the scale	
↓ ↓	(Press the ESC key to terminate calibration back to menu	
	ECF-1)	
150.00kg	Calibration procedure completed and the scale will return	
	back to weighing mode automatically	


ECF-2 Zero Calibration :


ECF-2	Press the 4 key to start Zero Calibration (Press the ESC
	key to exit back to weighing mode)
L→ ↓	
CALZ	Press the \checkmark key to calibrate zero point (Press the ESC key
	to terminate calibration back to menu ECF-2)
L→ ↓	
0.00kg	Zero Calibration procedure completed and the scale will
	return back to weighing mode automatically

ECF-3 SPAN Calibration :		
ECF-3		Press the 4 key to start Span Calibration (Press the ESC
		key to exit back to weighing mode)
	₽	- -


150.00kg	Use \triangleleft , \triangleright , \triangleleft , $0 \sim 9$ and then \triangleleft key to enter the weight to be	
	calibrated	
لۍ ↓	(Press the ESC key to terminate calibration back to menu	
	ECF-3)	
150.00kg	Place the required weight mass onto the scale as indicated on	
	display and press the \prec key to calibrate the scale	
له ↓	(Press the ESC key to terminate calibration back to menu	
	ECF-3)	
150.00kg	Calibration procedure completed and the scale will return	
	back to weighing mode automatically	
Standard Functions Setup : Press the TARE () and the PRINT () key in weighing mode to start Standard		

Press the TARE / ► and the PRINT / ↓ key in weighing mode to start Standard **Functions Setup** UF-1 Internal Value UF-2 Check Weighing UF-3 Auto Power-off UF-4 Backlight ♣UF-5 Hold UF-6 RS232 Output ••UF-7 ADC Update Rate ✤UF-8 Display Condition at Zero UF-9 Gravitational (G value) Pre-Calibration Net/Gross / PRINT / ≁ ↲ ZERO / < UNITS / ESC : ESC : ◀ TARE / 🕨 : ► UF-1 Press the ↓ key to start or press the ESC key to exit menu and back to weighing mode ► UF-2 Press the ↓ key to start or press the ESC key to exit menu and back to weighing mode î ◀ ►





Press the \checkmark key to continue or the ESC key to exit back to menu UF-1



Ъ

Press the ↓ key to see the battery voltage or the ESC key to exit back to menu UF-1

UF-1


Use ► and then ↓ keys to continue with other setups or press the ESC key to exit menu and back to weighing mode

UF-2 Check Weighing :

- 0000.0L Set LO (low) weight
- 0000.0H Set HI (high) weight
- O 000 Program I/O conditions
- X LO set as 0 will clear all check weigh values
- * Check weighing conditions can be set independently for each of the weighing units and counting mode
- ※ All settings will be saved until manually cleared
- ※ Last entry will be displayed before setup
- * This function is locked when UF-5 is set as "HOLD 1"



Press the \checkmark key to start or press the ESC key to exit menu and back to weighing mode



Use ◀,▶,▲,0~9 and then ↓ key to set LO weight value (Press the ESC key to exit the setup and back to menu UF-2) Use ◀,▶,▲,0~9 and then ↓ key to set HI weight value (Press the ESC key to exit the setup and back to menu UF-2) Use ◀,▶,▲,0~9 and then ↓ key to set I/O SET value (Press the ESC key to exit the setup and back to menu UF-2) Use ◀,▶ and then ↓ key to continue with other setups or press the ESC key to exit menu and back to weighing mode

UF-3 Auto Power-off :

AoFF 00 Auto power-off disable

AoFF 01 The scale turns off automatically in 1 minute when the scale is

not in operation and weight at 0

Auto power-off timer up to 99 minutes (AoFF01~AoFF 99)

※ Factory default: AoFF 10

UF-3	Press the \checkmark key to start or press the ESC key to exit menu
	and back to weighing mode

Use ◀.►.▲ and then ↓ key to enter Auto Power-off time (Press the ESC key to exit the setup and back to menu UF-3)

↲

AoFF10

JUF-3

Use \checkmark and then \checkmark key to continue with other setups or press the ESC key to exit menu and back to weighing mode

UF-4 Backlight :			
Lit oFF :Backligh	Lit oFF :Backlight off Lit A :Auto light up Lit on :Backlight on		
※ Factory default	: Lit A		
UF-4	Press the \checkmark key to start or press the ESC key to exit menu		
	and back to weighing mode		
له ↓			
Lit A	Use \blacktriangle and then \checkmark key to select backlight modes		
	(Press the ESC key to exit the setup and back to menu UF-4)		
	-		
UF-4	Use \triangleleft and then \triangleleft key to continue with other setups or		
	press the ESC key to exit menu and back to weighing mode		

UF-5 Hold :		
HOLD 0 Hold function off		
HOLD 1 Animal (motion) Hold function		
PCt XXX To set the range from $001 \sim 100$ of the animal hold		
(for HOLD 1 only)		
timEXX To set 1.2.4.8.16.32.64 times within the hold range		
(for HOLD 1 only)		
※ This function is locked when LF 6 is set as "Approval Version"		
※ Factory default: HOLD 0		
UF-5 Press the \checkmark key to start or press the ESC key to exit menu		
and back to weighing mode		
۲		
HOLD 0 Use \checkmark and then \checkmark key to select Hold modes		
(Press the ESC key to exit the setup and back to menu UF-5)		
< 1		
UF-5 Use \checkmark and then \checkmark key to continue with other setups or		

	press the ESC key to exit menu and back to weighing mode	
HOLD 1 mode :	_	
UF-5	Press the \checkmark key to start or press the ESC key to exit menu	
	and back to weighing mode	
<u> </u>		
HOLD 1	Use \blacktriangle and then \checkmark key to select Hold 1 mode	
	(Press the ESC key to exit the setup and back to menu UF-5)	
له ∳		
PCt <u>0</u> 10	PCt $\underline{0}10$ Use $4 > 4 = 0 = 9$ and then 4 key to enter the hold range	
	(Press the ESC key to exit the setup and back to menu UF-5)	
له ∳		
timE 8	Use \blacktriangle and then \checkmark key to select times	
	(Press the ESC key to exit the setup and back to menu UF-5)	
L→ ↓		
UF-5	Use \checkmark and then \checkmark key to continue with other setups or	
	press the ESC key to exit menu and back to weighing mode	

UF-6 RS232:

232	0	RS232 disable

- 232 1 Stable output Format 1
- 232 2 Stream output Format 1
- 232 3 Manual output Format 1
- 232 4 Stable output Format 2
- 232 5 Stream output Format 2
- 232 6 Manual output Format 2

RS232 Baud rate

- b 1200 Baud rate 1200
- b 2400 Baud rate 2400
- b 4800 Baud rate 4800
- b 9600 Baud rate 9600
- b19200 Baud rate 19200
- b38400 Baud rate 38400

Communication Protocol

UART signal of EIA-RS232	UART signal of EIA-RS232 C			
Format:	Format:			
1. Serial output: 1200 / 2400	/ 4800 / 9600 / 19200 / 38400 BPS			
2. Data bits : 8 BITS				
3. Parity bits : None				
4. Stop bits : 1 BIT				
Start bit Data bits Stop bits				
Format 1 (232 1 ~ 3):				
HEAD1 (2 BYTES)	HEAD2 (2 BYTES)			
OL - Over Load				
ST - Stable	NT - Net Weight			
US - Unstable	GS - Gross Weight			
Fixed 18 BYTES ASCII (kg g t lb) 1 2 1 1 2 3 4 5 6 7 8 1 2 1 2 HEAD1 , HEAD2 , DATA UNIT CR LF UNIT CR LF				
Fixed 21 BYTES ASCII (tl.T lboz) 1 2 1 1 2 3 4 5 6 7 8 9 1 2 3 4 1 2 HEAD1 HEAD2 HEAD2 DATA UNIT CR LF				
Fixed 19 BYTES ASCII (pcs) 1 2 1 1 2 3 4 5 6 7 8 1 2 3 1 2 HEAD1 HEAD2 HEAD2 DATA UNIT CR LF				
Output examples :				
1. Example +0.876 kg Stable net weight : S T , N T , + 0 0 . 8 7 6 k g 0D 0A				
2. Example -1.568 lb unstable gross weight : U S , G S , - 0 0 1 . 5 6 8 1 b 0D 0A				
3 Example -20. 5.40 lb oz unstable gross weight :				
S T , G S , - 1 0 . 0 5 . 4 0 1 b o z 0D 0A				
4 Example +1000 pcs stable net weight : S T , N T , + 0 0 1 0 0 p c s 0D 0A				

Format 2 (232 $4 \sim 6$):
Fixed 12 BYTES ASCII (kg g t lb) 1 2 3 4 5 6 7 8 1 2 1 2
DATA UNIT CR LF
Fixed 15 BYTES ASCII (tl.T lboz)
DATA UNIT CR LF
Fixed 13 BYTES ASCII (pcs)
DATA UNIT CR LF
Output examples :
1. Example +0.876 kg stable net weight :
+ 0 0 0 . 8 7 6 k g 0D 0A
2. Example -1.568 lb unstable gross weight :
- 0 0 1 . 5 6 8 1 b 0D 0A
3 Example -20. 5.40 lb oz unstable gross weight :
- 1 0 . 0 5 . 4 0 1 b o z 0D 0A
4 Example +1000 pcs stable net weight :
+ 0 0 0 1 0 0 0 p c s 0D 0A
× Factory default: 232 0
UF-6 Press the \checkmark key to start or press the ESC key to exit menu
and back to weighing mode
↓ _↓
$232 0$ Use \blacktriangle and then \checkmark key to enter RS232 output format
(Press the ESC key to exit the setup and back to menu UF-6)
↓ ↓
b 9600 Use ▲ and then ↓ key to select baud rate
(Press the ESC key to exit the setup and back to menu UF-6)
↓ ↓
UF-6 Use \checkmark and then \checkmark key to continue with other setups or
press the ESC key to exit menu and back to weighing mode

UF-7 ADC Update Rate :
SPEEd 1 Standard speed 15 hz
SPEEd 2 High speed 30 hz
SPEEd 3 Low speed 7.5 hz
X This function is locked when UF-5 is set as "HOLD 1"
X This function is locked when LF 6 is set as "Approval Version"
X Factory default: SPEEd 1
UF-7 Press the ← key to start or press the ESC key to exit menu
and back to weighing mode
SPEEd 1 Use ▲ and then ↓ key to select ADC speed
(Press the ESC key to exit the setup and back to menu UF-7)
UF-7 Use \checkmark and then \checkmark key to continue with other setups or
press the ESC key to exit menu and back to weighing mode
UF-8 Zero Weight Display Condition :
ZP 0 Off
ZP 1 One division not to display at zero
ZP 2 Two divisions not to display at zero
ZP 3 Three divisions not to display at zero
ZP 4 Four divisions not to display at zero
ZP 5 Five divisions not to display at zero
* This function is locked when UF-5 is set as "HOLD 1"
* This function is locked when LF 6 is set as "Approval Version"
※ Factory default: ZP 0
UF-8 Press the \checkmark key to start or press the ESC key to exit menu
and back to weighing mode
L→ ↓ ↓
$ZP = 0$ Use \bullet and then \bullet key to select how many divisions not to
display at zero
(Press the ESC key to exit the setup and back to menu UF-8)
Use \checkmark and then \checkmark key to continue with other setups or

press the ESC key to exit menu and back to weighing mode

UF-9 Standard Gravitational (G value) Pre-Calibration:

Approval Model: When the CAL switch is at OFF, 10 gravitational values can be entered and can be also recalled for reference. After 10 gravitational values have been filled, the scale will only allow recalling previous 10 values (-00- ~ -09-) for reference and adding new value will not be allowed. Internal Gravitational Calibration or LF1 Internal Weight Calibration has to be done to erase previously entered values.

Non-approval Model: Even the scale allows to do the Standard Calibration,


Gravitational Calibration can help to provide accurate scale when end users


received it without all the trouble to recalibrate the scale. Pre-calibration is allowed

when the scale is setup as non-approval model or the CAL switch is at ADJ

position. Gravitational value will be saved at -00- and will be replaced each time a new value has been entered.


- X Sender G value: Set it before Weight Calibration
- ※ Recipient G value: Set it after Weight Calibration
- * The G value will be denied when the value is greater than 9.83217 (Polar G value) or less than 9.78031 (Equator G value)
- [™] Factory Default: 9.79423






Approval Calibrations and Functions Setup (Lock section):


Turn on the scale and press and hold the ZERO / < key until the countdown
sequence becomes 1001, then release the ZERO / < key and the scale will show LF
1
LF 1 Weight Calibration
LF 2 Spec Calibration
LF 3 Linearity Calibration
LF 4 ADC Update Speed
LF 5 Zero Weight Display Condition
LF 6 Approval Conformity
LF 7 Gravitational (G value) Pre-Calibration
LF 8 Zero Weight Display Condition
※ CAL switch has to be ON
* Password is required to use Lock Section when LF 6 is set as "none" and CAL
switch is OFF
PRINT / ↓ : ↓ Net/Gross / ▲ : ▲
ZERO / I : I UNITS / ESC : ESC
TARE / \blacktriangleright : \blacktriangleright






LF 2 Spec Calibration:		
First step 262144 Display Internal Value		
Second step $ \underline{1 \ 0 \ 0 \ 0 \ 1} $ A B C D E F		
A : Metric System0 : None $1 : kg$ $2 : T$ $3 : g$		
B : American System 0 : None 1 : lb 2 : lb oz		
C: Other Units 0: None 1: TW Kg 2: HK Kg 3: VISS		
D:PCS 0:Off		
1 : On		
E : Duo range 0 : Off		
1 : MULTI INTERVAL		
2 : MULTIRANGE		
F : Calibration Unit 1 : Metric units as calibration unit		
2 : American units as calibration unit		

* Ib oz unit cannot be selected as calibration unit * The scale will not allow to continue to the next setup step if an error has occurred during the programming Third step 000000kg Use 4 > 4 0 - 9 and then 4 key to enter the max. capacity → Showing the calibration unit Forth step Use \checkmark keys to move the position of the decimal point d ().()d () ()()d (),()d ().()()()Fifth step div ()1 Press the ▲ key to select division div ()2 div ()5div 10 div 2(50 div X After entering LF 2, the scale will display the last saved setup. All steps have to be completed to save the changes, otherwise the scale will keep the last setup ※ Proceed with Weight Calibration after LF2 Spec Calibration LF 2 Press the \checkmark key to start and will display the internal value or press the ESC key to exit menu and the scale will restart automatically ୶ 262144 Press the \checkmark key to continue with the setup (Press the ESC key to exit the setup and back to menu LF 2) ℯ 100001 Use 4 > 4 = 0 - 9 and then 4 key to select weighing units ┛ (Press the ESC key to exit the setup and back to menu LF 2) 00000kg Use 4 > 4 0 - 9 and then 4 key to enter the max. capacity ₽ (Press the ESC key to exit the setup and back to menu LF 2) 0.0kg d Use \triangleleft and then \triangleleft key to move the decimal point



terminate calibration back to menu LF 3)



3)

Place 1/3 weight mass of full capacity onto the scale and press the ► key to calibrate 1/3 of the capacity

(Press the ESC key to terminate calibration back to menu LF


Place 2/3 weight mass of full capacity onto the scale and press the \blacktriangleright key to calibrate 2/3 of the capacity

W 2

▲ ↑ ↓ ▶	(Press the ESC key to terminate calibration back to menu LF
	3)
W 3	Place weight mass of full capacity onto the scale and press
	the ► key to calibrate full capacity 放
↓ ↓ ▶	(Press the ESC key to terminate calibration back to menu LF
	3)
W 4	Press the 🖌 key to complete linearity calibration
به ↓	(Press the ESC key to terminate calibration back to menu LF
	3)
LF 3	Use \checkmark and then \checkmark key to continue with other setups or
	press the ESC key to exit menu and the scale will restart
	automatically

LF 4 ADC Update Rate :

- SPEEd 1 Standard speed 15 hz
- SPEEd 2 High speed 30 hz
- SPEEd 3 Low speed 7.5 hz
- % This function is locked when UF-5 is set as "HOLD 1"
- [™] Factory default: SPEEd 1




LF 5 Zero Weight Display Condition :

- ZP 0 Off
- ZP 1 One division not to display at zero
- ZP 2 Two divisions not to display at zero
- ZP 3 Three divisions not to display at zero

- ZP 4 Four divisions not to display at zero
- ZP 5 Five divisions not to display at zero
- * This function is locked when UF-5 is set as "HOLD 1"

[∗] Factory default: ZP 0




LF 6 Approval Conformity:

nonE Non-approval version; Initial Zero not restricted, Standard calibration allowed

oiML EC approval; Initial Zero FULL SCALE $\pm 10\%$, Manual Zero FULL

SCALE $\pm 2\%$, No standard calibration allowed

✗ Factory default: nonE



LF 7 Internal Gravitational (G value) Pre-Calibration:

X Sender G value: Set it before Weight Calibration

X Recipient G value: Set it after Weight Calibration X The G value will be denied when the value is greater than 9.83217 (Polar G value) or less than 9.78031 (Equator G value) [™] Factory Default: 9.79423 LF7 Press the 4 key to start or press the ESC key to exit menu and the scale will restart automatically ₽ -00-The display will show the number of pre-calibration for a second 9.79423 Press the \checkmark key to continue ₽ 9.79423 Use 4 > 4 = 0 - 9 and then 4 key to enter the G value Ł (Press the ESC key to exit the setup and back to menu LF 7) LF Use \triangleleft and then \triangleleft key to continue with other setups or press the ESC key to exit menu and the scale will restart automatically

LF 8 Initial Zero:

- SEtZ Y Reset zero point every time the scale has been switched on
- SEtZ n Zero point reset off
- [™] Factory Default: SEtZ Y

LF 8	Press the \checkmark key to start or press the ESC key to exit menu
	and the scale will restart automatically
↓ ↓	_
SEtZ Y	Use ▲ and then ↓ key to select initial zero mode
	(Press the ESC key to exit the setup and back to menu LF 8)
L→ ↓	_
LF 8	Use \checkmark and then \checkmark key to continue with other setups or
	press the ESC key to exit menu and the scale will restart
	automatically